

6043

Rocky Flats Plant
North American Space Operations
Rockwell International Corporation
P.O. Box 464
Golden, Colorado 80402-0464
(303) 966-7000

Rockwell
International

Contractor to U.S. Department of Energy

December 22 1987

87 RF 4808

Mr. Albert E. Whiteman
Area Manager
DOE RFAO

DATA SUPPLEMENT TO 881 HILLSIDE AREA REMEDIAL INVESTIGATION REPORT

Enclosed are six (6) copies of the data which were not available for inclusion in the July 1 1987 draft Remedial Investigation Report for the High Priority Sites (881 Hillside Area). Four of the copies have been provided for transmittal to the Department of Health (CDH) and Environmental Protection Agency (EPA) by December 31 1987 in accordance with verbal agreements and the schedule CDH presented at the September 29 1987 State Exchange Meeting.

The newly available data include radionuclide results for all soil samples (65) plus complete analytical results for 9 of those samples. Listed below are the sample identification numbers for the enclosed analytical data. The sample identification numbering system is explained in Appendix C (Figure C 1) of the report. Map of the boring locations is provided in Section 4 Plate 4 1.

Radionuclide results are included for the following soil samples

BH018704WS
BH018710WS
BH018701WT

BH07871013
BH078708BR
BH028718BR
BH02871420
BH02870012
BH02871214

BH048719BR
BH048715CT
BH04870010
BH048710WT

BH17870005
BH158726BR

BH03870009
BH038709CT
BH038702WT
BH038712BR
BH05870005
BH058708BR
BH058705CT
BH068730BR
BH06870010
BH068726CT
BH06871020

BH108723BR
BH10870010
BH10871020
BH108720CT

BH138714BR

ADMIN RECORD

A-OU01-000586

A E Whiteman
page 2

87 RF 4808

BH15870005
BH088710BR
BH15870510
BH178705CT
BH08870007
BH088707CT
BH178708BR

BH138711CT
BH13870010
BH098706WT
BH09870010
BH098714BR
BH098711CT

BH168702CT
BH118714WT
BH168706BR
BH118711CT
BH11870010
BH11870206


BH128705BR
BH128702CT
BH148703W1
BH148708W2
BH148709BR
BH148706CT

Complete analytical results (radionuclides volatile organics
semi volatile organics metals) are included for the following soil
samples

BH02871214
BH02870012
BH028718BR
BH148708W2
BH148706CT
BH148709BR
BH148703W1
BH098711CT
BH138711CT

These data were requested by CDH before the end of December and will
be included in the revised 881 Hillside Remedial Investigation Report
in February

If you have any questions, please call Tom Greengard at
extension 7121



K B McKinley
RCRA/CERCLA

Enc

Orig & 7cc - A E Whiteman